

## 9257 CT PEX Clamp Removal Tool Instructions

A Member of the **Oetiker Group**

### FOR CLAMP CUTTING ONLY

1. Place jaw tips on either side of the clamp ear or on a single leg (Fig. 1)
2. Squeeze handles (Fig. 2)
3. Cut through clamp (Fig. 3)
4. Remove clamp



Fig. 1

**CAUTION: Wear Eye Protection**




Fig. 2

**CAUTION: Cut clamps have sharp edges.**




Fig. 3

